



WHITE



BLACK



C: 100% M: 10% K: 10%



M: 100% Y: 100%

**CAUTION: Turn off power before use.**

1. Strip stranded wires 20mm (0.79").
2. Pretwisting unnecessary.  
Hold stripped wires together with ends even  
(lead stranded wires slightly).
3. Align any frayed strands or conductors.
4. Screw on connector—push wires firmly into  
connector when starting.
5. To be sold only with installation instructions.

623-008



Listed as splicing wire connectors  
on the following stranded wire combinations:  
Voltage: 600V Max. Building Wiring; 1000V Max. Signs / Luminaries

## Winged Wire Connectors

Quantity: 50



LISTED FOR USE WITH  
COPPER TO COPPER

Insulation operating temperature:  
105°C (221°F) Max.

3 #10 w/ 1 #8  
3 #12 w/ 1 #10  
1 #12 w/ 2 #10  
2 #12 w/ 2 #10  
3 #12 w/ 2 #10  
1 #12 w/ 3 #10  
2 #12 w/ 3 #10  
2 #10  
4 #10

12-8 AWG; 600V Max. Building Wiring;  
1000V Max. Signs / Luminaries



Made in China



63 mm

203 mm