## **WARNING**

This unit is equipped with a DiversiTech condensate overflow shut-off switch installed on the drain pan or drain line. If unit is not operating, lift switch/cap assembly to test. If unit runs, drain needs to be cleared. Clean and test every 180 days.



www.diversitech.com



Miller-Myers Design Group 3640 Park 42 Drive Cincinnati, OH 45241 513.733.6900 Jim Fenster jimfenster@miller-myersdesign.com Client: Product Name: Standex Electronics

DiversiTech CS Warning Sticker

Product Number:

ei.

File Date: 01.03.13

Prints Black on Fluorescent Chartreuse