



ITEM NO.	PART NUMBER	DESCRIPTION	Default/ QTY.
1	MNT-A10-02-288	Angle Iron Stand 12 J-Bar	4
2	MNT-A10-03-286	Angle Iron Stand Extension Bar	2
3	MNT-A10-02-289	Iron Stand 27in Angle Iron Arm	2
4	QSR008	1/4-20x1/2in Zinc Hex Bolts	8
5	QSR015	1/4in Bonded Washers	8
6	MNT-A10-03-285	Angle Iron Stand 6x6 Feet	4
7	MNT-A10-04-283	6x1.5 - Mini Split Rubber Foot	8
8	QSR021	3/8-16x2in Carriage Bolt Zinc	4
9	QSR035	3/8in Bonded Washer	4
10	QSR026	3/8in Zinc Hex Nut	8
11	QSR017	3/8-16x1 3/4in Hex Bolt Galv	4
12	QSR034	3/8in Split Washer Galv	4
13	QSR025	3/8in Galvanized Hex Nuts	4

## NOTE - ALL ASSEMBLY HARDWARE IS INCLUDED

| INCHES | [MILLIMETERS] | X = ±0.1 | [X = ± 2.5 ] | .XX = ±0.01 | [.X = ± 1.3 ] | .XXX = ±0.005 | [.XX = ±0.13]





CONFIDENTIAL - PROPRIETARY - DO NOT COPY	MAIL
THE INFORMATION SET FORTH IN THIS DOCUMENT AND RELATED	
INFORMATION IS THE CONFIDENTIAL PROPERTY OF DIVERSITECH CORPORATION, AND IS NOT TO BE COPIED OR REPRODUCED OR DISTRIBUTED IN ANY FORM WITHOUT PRIOR WRITTEN PERMISSION FROM DIVERSITECH CORPORATION.	DWG.
DO NOT SCALE DRAWING	

PΥ	MATERIAL:	WEIGHT
TED CH	DWG. NO.	GMS.
OR .	QUICK SLING STAND - 4002	REV.
	MODEL NO. QSTD4002	
		2 OF 2